COMPLETION REPORT

1	Name of Work	Maintenance and Repairs to the new park at Gunduthopu in Dasarahalli Constituency
2	Sanctioned Estimate	**Rs1.55 lakhs**
3	Head of A/c which is chargeable	P-0298
4	Entrustment Order No. & Date	EE/ELE/DZ/WO/000002/19-20, Dt:22/01/2020
5	Name of Contractor	M/s.Sri Lakshminarasimha Electricals
6	i. Time stipulated for j. Completion of Work	
7	b.Delay in execution of work	Not Applicable
8	Measurement recorded in	M.B No: 3404/19-20 340305 to 340308
9	Check Measurement of Asst.Exe.Engr/.Executive Engineer on	20/03/2020
10	Name of the Office/Office in charge of the Work a) Asst.Eng/Jr.Engineer	Executive Engineer (Ele),Yelahanka Zone Mr.K.N.Babu Reddy
	b) Asst.Executive Engineer	Gurappa.Y.Doddamani

Sanctioned Estimated Amount **1.55** Lakhs	Amount Claims as per actually vide as per Bills **1,12,807/-**	DIFFERENCE		Remarks
		EXCESS	SAVINGS	
		-		

Certified that the above has been completed within the stipulated time noted in the work order.

1. Certified that the contractor has delayed and completed the work for which necessary time has been recovered.
2. Certified that the above has been executed by the contractor satisfactorily in accordance with the specification as embedded in the agreement.

K.N.Babu Reddy
Assistant Engineer(Ele)
Dasarahalli Zone, BBMP

Assistant Executive Engineer(Ele)
Dasarahalli Zone, BBMP

Executive Engineer(Ele)
Dasarahalli Zone, BBMP

Scanned with CamScanner